

**Flood Control Project Maintenance
Levee Inspections**

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR Erosion Survey

San Joaquin River Basin

RD2058	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 2058						
Pescadero	U	6.71				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
Vegetation	1.17	0.04	1.33	19.82%		
Trim / Thin Trees	0.35	0.18	1.07	15.95%		
Encroachments	0.24		0.24	3.58%	0.06	
Animal Control	0.12	0.01	0.16	2.38%		
DWR Erosion Survey	0.05		0.05	0.75%		
<i>LMA Totals:</i>	1.93	0.23	2.85	42.47%	0.06	0.00

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Fall 2009 Levee Inspection Results

Reclamation District No. 2058 Pescadero

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			U	

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2009 Levee Inspection Results

Reclamation District No. 2058 Pescadero

Waterway			Bank	Unit Miles
Unit No. 01 Paradise Cut			Left	6.71
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			U	
Date of Inspection	4/20/2009		10/6/2009	
DWR Inspector	Richard Willoughby		John Paasch	
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 2058 Pescadero

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut				Left	6.71	10/06/2009 10/06/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	0.15	Earthen Levee	Vegetation	WS	A	Inspector Comments: Vegetation on water side of levee crown is maintained to allow access and visibility.	37.801590 ° -121.420799 °	37.803411 ° -121.419412 °	945
2	0.05	0.05	Earthen Levee	Encroachments	WS	M	Debris Inspector Comments: Rusted metal pipe and concrete is present within 20-ft of crown.	37.802209 ° -121.420356 °	37.802209 ° -121.420356 °	946 Y
3	0.12	0.12	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows. Inspector Comments: Burrow hole ob water side. Leve is extremely wide at this point.	37.803012 ° -121.419732 °	37.803012 ° -121.419732 °	947 Y
4	0.15	0.18	Earthen Levee	Encroachments	WS	M	Prunings Inspector Comments: Prunings piled on water side hinge point are obstructive.	37.803416 ° -121.419411 °	37.803876 ° -121.419042 °	948 Y
5	0.19	0.21	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	37.803853 ° -121.419083 °	37.804025 ° -121.418712 °	4
6	0.26	0.34	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	37.804654 ° -121.417868 °	37.804430 ° -121.416532 °	944
7	0.27	0.29	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	37.804553 ° -121.417967 °	37.804657 ° -121.417567 °	936 Y
8	0.41	0.43	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Brush within 20-ft of levee crown impedes access and visibility.	37.803831 ° -121.415718 °	37.803668 ° -121.415530 °	949 Y
9	0.43	0.46	Earthen Levee	Vegetation	WS	A	Inspector Comments: Vegetation within 20-ft of water side slope has been maintained to permit visibity and access.	37.803643 ° -121.415518 °	37.803280 ° -121.415129 °	951 Y
10	0.44	0.44	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Brush within 10-ft of landside toe limits access and visibility.	37.803598 ° -121.415465 °	37.803598 ° -121.415465 °	950
11	0.50	0.71	Earthen Levee	Vegetation	CR	M	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Annual vegetation removal does not appear to have been done.	37.802834 ° -121.414550 °	37.801834 ° -121.411244 °	953
12	0.50	0.71	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Annual vegetaion maintenance does not appear to have been done.	37.802903 ° -121.414648 °	37.801834 ° -121.411244 °	952 Y
13	0.64	0.71	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	37.801942 ° -121.412543 °	37.801835 ° -121.411244 °	954

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 2058 Pescadero

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 Paradise Cut						Left	6.71	10/06/2009 10/06/2009	John Paasch	
LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
14	0.77	1.03	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Vegetaion within 10-ft of levee toe blocks visibility.	37.801752 ° -121.410145 °	37.801394 ° -121.405569 °	955
15	0.77	0.83	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	37.801749 ° -121.410127 °	37.801627 ° -121.409150 °	956
16	0.82	0.93	Earthen Levee	Trim / Thin Trees	WS	U	Trim and thin trees to allow visibility of the ground and room to flood fight.	37.801687 ° -121.409448 °	37.801436 ° -121.407456 °	14 Y
17	0.83	0.83	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	37.801618 ° -121.409200 °	37.801618 ° -121.409200 °	937
18	0.97	1.05	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	37.801378 ° -121.406636 °	37.801442 ° -121.405179 °	957
19	1.12	1.17	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	37.801687 ° -121.404178 °	37.801900 ° -121.403308 °	5
20	1.22	1.22	Earthen Levee	Vegetation	WS	U	Remove the wild growth other than native grasses from the levee slopes.	37.802253 ° -121.402242 °	37.802253 ° -121.402242 °	958 Y
21	1.29	1.33	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	37.802495 ° -121.401157 °	37.802652 ° -121.400542 °	6
22	1.30	1.30	Earthen Levee	Vegetation	WS	U	Remove the wild growth other than native grasses from the levee slopes.	37.802581 ° -121.400861 °	37.802581 ° -121.400861 °	15 Y
23	1.34	1.34	Earthen Levee	Vegetation	WS	U	Remove the wild growth other than native grasses from the levee slopes.	37.802743 ° -121.400188 °	37.802743 ° -121.400188 °	959 Y
24	1.35	1.38	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	37.802737 ° -121.400201 °	37.802886 ° -121.399551 °	16
25	1.49	1.52	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	37.803363 ° -121.397543 °	37.803469 ° -121.397107 °	960 Y
26	1.69	1.72	Earthen Levee	Vegetation	WS	M	Elderberries are blocking visibility and flood fight capability.	37.804158 ° -121.394169 °	37.804329 ° -121.393612 °	961
27	1.72	1.74	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	37.804340 ° -121.393570 °	37.804431 ° -121.393256 °	962
28	1.80	1.84	Earthen Levee	Trim / Thin Trees	WS	U	Trim and thin trees to allow visibility of the ground and room to flood fight.	37.804658 ° -121.392300 °	37.804795 ° -121.391521 °	17
29	1.89	1.92	Earthen Levee	Trim / Thin Trees	WS	U	Thin trees to allow visibility of the ground and room to flood fight.	37.804783 ° -121.390579 °	37.804720 ° -121.390123 °	963 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 2058 Pescadero

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut				Left	6.71	10/06/2009 10/06/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
30	1.99	2.03	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	37.804497 ° -121.388905 °	37.804350 ° -121.388252 °	964
31	2.15	2.15	Supplemental	DWR Erosion Survey	WS	M	Inspector Comments: 2009: Longitudinal crack where air vent is located; portion of vertical pipe exposed; small chunks of concrete debris on lower 1/2 of slope; [2009 SiteID:RD2058U1RM1.78]	37.803769 ° -121.386341 °	37.803769 ° -121.386341 °	1
32	2.42	2.42	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	37.802793 ° -121.381354 °	37.802793 ° -121.381354 °	965
33	2.45	2.45	Earthen Levee	Encroachments	LS	M	Prunings Inspector Comments: Tumble weeds piled on landside slope.	37.802683 ° -121.380943 °	37.802683 ° -121.380943 °	966 Y
34	2.48	2.60	Earthen Levee	Vegetation	LS	A	Inspector Comments: Levee vegetation is maintained to allow access and visibility.	37.802568 ° -121.380447 °	37.802104 ° -121.378355 °	967 Y
35	2.73	2.73	Earthen Levee	Encroachments	LS	M	Prunings Inspector Comments: Tumble weeds on slope.	37.801581 ° -121.376026 °	37.801581 ° -121.376026 °	968
36	2.80	2.80	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	37.801329 ° -121.374926 °	37.801329 ° -121.374926 °	969 Y
37	2.92	2.96	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	37.800805 ° -121.372815 °	37.800641 ° -121.372152 °	970
38	3.19	3.19	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	37.798877 ° -121.368653 °	37.798877 ° -121.368653 °	938
39	3.28	3.40	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	37.798020 ° -121.367605 °	37.796495 ° -121.366342 °	971
40	3.49	3.49	Earthen Levee	Vegetation	WS	A		37.795467 ° -121.365598 °	37.795467 ° -121.365598 °	972 Y
41	3.67	3.74	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	37.793127 ° -121.364236 °	37.792214 ° -121.363698 °	973
42	3.76	3.76	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Photo of flagged bushes obstructing visibility and access	37.791856 ° -121.363514 °	37.791856 ° -121.363514 °	974 Y
43	3.77	3.77	Earthen Levee	Vegetation	WS	U	Elderberries are blocking visibility and flood fight capability.	37.791745 ° -121.363553 °	37.791745 ° -121.363553 °	939
44	3.96	3.96	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	37.789398 ° -121.361713 °	37.789398 ° -121.361713 °	975 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 2058 Pescadero

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut						Left	6.71	10/06/2009 10/06/2009	John Paasch

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
45	3.97	4.03	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Mangled barbed wire fence on levee slope	37.789369 ° -121.361644 °	37.789005 ° -121.360694 °	976
46	4.10	4.10	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	37.788730 ° -121.359537 °	37.788730 ° -121.359537 °	9
47	4.10	4.10	Earthen Levee	Encroachments	LS	M	Debris Inspector Comments: Straw, plastic and cuttings on levee slope and crown.	37.788803 ° -121.359316 °	37.788803 ° -121.359316 °	977 Y
48	4.30	4.30	Earthen Levee	Trim / Thin Trees	WS	C	Trim trees to at least five feet above ground level.	37.789372 ° -121.356012 °	37.789372 ° -121.356012 °	940
49	4.49	4.53	Supplemental	DWR Erosion Survey	WS	M	Inspector Comments: 2009: No change observed; berm re-measured at 20'; recommend annual assessment and monitoring of erosion site, per CLRO CES Evaluation 2008 Report; site # same as RM4.0,LM4.51; previously rated "U" [2009 SiteID:RD2058U1RM3.97]	37.789810 ° -121.352490 °	37.789810 ° -121.352490 °	2
50	4.58	4.58	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	37.789263 ° -121.351352 °	37.789263 ° -121.351352 °	978 Y
51	4.81	4.81	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	37.786005 ° -121.350508 °	37.786005 ° -121.350508 °	941
52	4.83	4.83	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	37.785810 ° -121.350279 °	37.785810 ° -121.350279 °	979 Y
53	4.87	4.87	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	37.785190 ° -121.350078 °	37.785190 ° -121.350078 °	11
54	4.93	4.93	Earthen Levee	Trim / Thin Trees	WS	C	Trim trees to at least five feet above ground level.	37.784730 ° -121.349510 °	37.784730 ° -121.349510 °	12
55	4.97	4.97	Earthen Levee	Animal Control	WS	U	Exterminate rodents and backfill and compact or grout burrows. Inspector Comments: photos	37.784382 ° -121.348614 °	37.784382 ° -121.348614 °	980 Y
56	5.11	5.15	Earthen Levee	Encroachments	WS	M	Prunings Inspector Comments: photo of tumble weeds	37.783405 ° -121.346608 °	37.783094 ° -121.345797 °	981 Y
57	5.21	5.21	Earthen Levee	Trim / Thin Trees	WS	C	Trim trees to at least five feet above ground level. Inspector Comments: Trees have been trimmed.	37.782853 ° -121.345142 °	37.782853 ° -121.345142 °	942
58	5.26	5.26	Earthen Levee	Trim / Thin Trees	WS	C	Trim trees to at least five feet above ground level.	37.782658 ° -121.344190 °	37.782658 ° -121.344190 °	943
59	5.37	5.37	Earthen Levee	Encroachments	WS	M	Garbage	37.782340 ° -121.342170 °	37.782340 ° -121.342170 °	982 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 2058 Pescadero

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 Paradise Cut						Left	6.71	10/06/2009 10/06/2009	John Paasch	

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
60	5.62	5.73	Earthen Levee	Encroachments	WS	M	Prunings	37.779675 ° -121.339906 °	37.778479 ° -121.339106 °	983
61	6.00	6.50	Earthen Levee	Vegetation	LS	A	Inspector Comments: Levee is free of vegetation	° °	° °	986 Y
62	6.01	6.01	Earthen Levee	Encroachments	WS	M	Garbage Inspector Comments: No change since last inspection.	37.775578 ° -121.336005 °	37.775578 ° -121.336005 °	13 Y
63	6.42	6.42	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	37.772047 ° -121.330188 °	37.772047 ° -121.330188 °	985 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	10/06/2009 10/06/2009	John Paasch

Levee Mile Report Line	2
Start Levee Mile	0.05
End Levee Mile	0.05
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Photo of trash.

jpaasch_20091015_16.jpg



Levee Mile Report Line	3
Start Levee Mile	0.12
End Levee Mile	0.12
Location	Water Side
Category	Earthen Levee
Item	Animal Control

Photo of burrow hole on water side.

jpaasch_20091015_17.jpg



Levee Mile Report Line	4
Start Levee Mile	0.15
End Levee Mile	0.18
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Photo of tree prunings on levee hinge point.

jpaasch_20091015_18.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 2058 Pescadaro

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	10/06/2009 10/06/2009	John Paasch

Levee Mile Report Line	7
Start Levee Mile	0.27
End Levee Mile	0.29
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Photo of trees and thick brush on water side slope of levee.

jpaasch_20091016_39.jpg



Levee Mile Report Line	8
Start Levee Mile	0.41
End Levee Mile	0.43
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Brush near crown on waterside slope.

jpaasch_20091016_38.jpg



Levee Mile Report Line	9
Start Levee Mile	0.43
End Levee Mile	0.46
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Maintained water side slope.

jpaasch_20091015_19.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	10/06/2009 10/06/2009	John Paasch

Levee Mile Report Line	12
Start Levee Mile	0.50
End Levee Mile	0.71
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Photo of vegetation on landside slope and toe.

jpaasch_20091016_40.jpg



Levee Mile Report Line	16
Start Levee Mile	0.82
End Levee Mile	0.93
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Photo of dense trees on waterside slope.

jpaasch_20091016_41.jpg



Levee Mile Report Line	20
Start Levee Mile	1.22
End Levee Mile	1.22
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Photo of dense brush completely obstructing visibility and access.

jpaasch_20091016_42.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	10/06/2009 10/06/2009	John Paasch

Levee Mile Report Line	22
Start Levee Mile	1.30
End Levee Mile	1.30
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Dense vegetation.

jpaasch_20091016_43.jpg



Levee Mile Report Line	23
Start Levee Mile	1.34
End Levee Mile	1.34
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Dense vegetation.

jpaasch_20091016_44.jpg



Levee Mile Report Line	25
Start Levee Mile	1.49
End Levee Mile	1.52
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Photo of minimally acceptable vegetation on water side slope.

jpaasch_20091016_45.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	10/06/2009 10/06/2009	John Paasch

Levee Mile Report Line	29
Start Levee Mile	1.89
End Levee Mile	1.92
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Trees on waterside slope should be trimmed to allow access and visibility 20-ft from crown.

jpaasch_20091016_37.jpg



Levee Mile Report Line	33
Start Levee Mile	2.45
End Levee Mile	2.45
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Photo of cleared vegetation piled on levee slope. This impedes access.

jpaasch_20091015_20.jpg



Levee Mile Report Line	34
Start Levee Mile	2.48
End Levee Mile	2.60
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Photo of acceptable vegetation maintenance.

jpaasch_20091016_34.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	10/06/2009 10/06/2009	John Paasch

Levee Mile Report Line	36
Start Levee Mile	2.80
End Levee Mile	2.80
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Photo of vegetation obstructing access and visibility on waterside slope within 20-ft of levee crown .

jpaasch_20091016_36.jpg



Levee Mile Report Line	40
Start Levee Mile	3.49
End Levee Mile	3.49
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Photo of well maintained levee section.

jpaasch_20091016_35.jpg



Levee Mile Report Line	42
Start Levee Mile	3.76
End Levee Mile	3.76
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Flagged bushes on waterside slope.

jpaasch_20091016_32.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	10/06/2009 10/06/2009	John Paasch

Levee Mile Report Line	44
Start Levee Mile	3.96
End Levee Mile	3.96
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees

Photo of trees needing trimming to allow access and visibility.

jpaasch_20091016_33.jpg



Levee Mile Report Line	47
Start Levee Mile	4.10
End Levee Mile	4.10
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Photo of prunings and straw on levee crown. Crown and slopes should be clear of obstructions.

jpaasch_20091016_21.jpg



Levee Mile Report Line	50
Start Levee Mile	4.58
End Levee Mile	4.58
Location	Water Side
Category	Earthen Levee
Item	Animal Control

Small animal burrows on water side slope.

jpaasch_20091016_22.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	10/06/2009 10/06/2009	John Paasch

Levee Mile Report Line	52
Start Levee Mile	4.83
End Levee Mile	4.83
Location	Land Side
Category	Earthen Levee
Item	Animal Control

Animal burrows on landside slope.

jpaasch_20091016_23.jpg



Levee Mile Report Line	55
Start Levee Mile	4.97
End Levee Mile	4.97
Location	Water Side
Category	Earthen Levee
Item	Animal Control

Photo of animal burrows on waterside slope.

jpaasch_20091016_24.jpg



Levee Mile Report Line	56
Start Levee Mile	5.11
End Levee Mile	5.15
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Photo of prunings on landside hinge point.

jpaasch_20091016_26.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	10/06/2009 10/06/2009	John Paasch

Levee Mile Report Line	59
Start Levee Mile	5.37
End Levee Mile	5.37
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Photo of garbage on waterward slope.

jpaasch_20091016_25.jpg



Levee Mile Report Line	61
Start Levee Mile	6.00
End Levee Mile	6.50
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Photo showing cleared levee.

jpaasch_20091016_30.jpg



Levee Mile Report Line	62
Start Levee Mile	6.01
End Levee Mile	6.01
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Garbage on waterward slope at LM 6.01 is still present during Fall 2009 inspection.

jpaasch_20091006_4.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	10/06/2009 10/06/2009	John Paasch

Levee Mile Report Line	63
Start Levee Mile	6.42
End Levee Mile	6.42
Location	Land Side
Category	Earthen Levee
Item	Animal Control

Photo of animal burrows near stump.

jpaasch_20091016_29.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected